

04 October 2024

ErSed Reference: 22004-ERMR-02-241004

Steven Avramov Development Manager, the GPT Group Level 51, 25 Martin Place Sydney NSW 2000, Australia

Re: SSD 10272349 - Yiribana Logistics Estate

Environmental Representative: Monthly Report (ERMR #2)

Condition of Approval A33(I) for SSD 10272349 requires that the ER:

"prepare and submit to the Planning Secretary and other relevant regulatory agencies, for information, an **Environmental Representative Monthly Report** providing the information set out in the Environmental Representative Protocol under the heading 'Environmental Representative Monthly Reports'.

The **Environmental Representative Monthly Report** must be submitted within seven calendar days following the end of each quarter for the duration of the ER's engagement for the development, or as otherwise agreed with the Planning Secretary.

This report constitutes the monthly report for the period 1-30 September 2024.

The report is to be provided to the Planning Secretary via the major projects website.

Please contact me if you require further information.

Sincerely

Carl Vincent

Principal (ErSed Environmental Pty Ltd) Environmental Representative for SSD 10272349

SSD 10272349 - Yiribana Logistics Estate: Environmental Representative Monthly Report (ERMR # 2) For the period 1 September 2024 to 30 September 2024



1							
1.	Construction activities carried	Construction activities are currently being performed by Burton Contractors. The following works were being undertaken during the reporting period:					
	out during the reporting period	 Pad 1 (warehouse 1) topsoil strip and bulk earthworks Pad 3 (warehouse 3) topsoil strip 					
		 ESCP Rev 2.0 implementation which includes construction of warehouse 2 and 3 basins, diversion drains and slit fencing 					
		 Demolition of concrete driveway in warehouse 3. 					
2.	Proposed	The following works are expected in the next period:					
	upcoming						
	construction	Continue bulk earthworks in pad 1 and topsoil strip in pad 3					
	works (where	Construction of pad 4 (warehouse 4) basin and diversion drains					
	known)	Construction of piling platforms for pad 1 and 3 Tangail string and hull parthursely in pad 2 (warehouse 2)					
		Topsoil strip and bulk earthworks in pad 2 (warehouse 2).					
3.	ER activities undert	aken during this reporting period.					
	Site inspections	During the reporting period, ER carried out the following inspections:					
		SSD 10272349 Key Observations					
		20/09/2024 • Bulk earthworks (Warehouse #1) have commenced					
		 Establishment of ERSED controls for Warehouse # 3 undertaken with B26 letter issued (reference 22024-GPT-B26 -20_9_24) 					
		Importance of dust control and stabilising work areas when complete.					
		Clearing activities advanced					
		Monitoring stations for air and noise implemented					
		A selection of photographs taken as part of inspections is provided, with comments, at item 14.					
	Audits undertaken	The following Audits were undertaken by the ER in the period.					
		Audits by Others is detailed at Part 4. Following:					
		NIL					
		Please refer to Section 9 for further information.					
	Audits/						
	Inspections by	CPESC monthly report as required by Condition A33.					
	<u>Others</u>						
		30/09/2024 The ESC inspection undertaken on GPT – Yiribana Site reviewed the progression of					
		works under the occupation of Burtons Contractors.					
		 works under the occupation of Burtons Contractors. The inspection reviewed the establishment on the site and the 					
		 works under the occupation of Burtons Contractors. The inspection reviewed the establishment on the site and the implementation of initial erosion and sediment controls and basins 					
		 works under the occupation of Burtons Contractors. The inspection reviewed the establishment on the site and the implementation of initial erosion and sediment controls and basins associated with the WH1, WH3 and WH2 Lots. The earthworks for WH1 					
		 works under the occupation of Burtons Contractors. The inspection reviewed the establishment on the site and the implementation of initial erosion and sediment controls and basins associated with the WH1, WH3 and WH2 Lots. The earthworks for WH1 Lot have commenced and are progressing to final design levels. 					
		 works under the occupation of Burtons Contractors. The inspection reviewed the establishment on the site and the implementation of initial erosion and sediment controls and basins associated with the WH1, WH3 and WH2 Lots. The earthworks for WH1 Lot have commenced and are progressing to final design levels. A review of the controls in relation to the proposed staging of works on 					
		 works under the occupation of Burtons Contractors. The inspection reviewed the establishment on the site and the implementation of initial erosion and sediment controls and basins associated with the WH1, WH3 and WH2 Lots. The earthworks for WH1 Lot have commenced and are progressing to final design levels. 					
		 works under the occupation of Burtons Contractors. The inspection reviewed the establishment on the site and the implementation of initial erosion and sediment controls and basins associated with the WH1, WH3 and WH2 Lots. The earthworks for WH1 Lot have commenced and are progressing to final design levels. A review of the controls in relation to the proposed staging of works on the site was undertaken to ensure effective control implementation and 					
		 works under the occupation of Burtons Contractors. The inspection reviewed the establishment on the site and the implementation of initial erosion and sediment controls and basins associated with the WH1, WH3 and WH2 Lots. The earthworks for WH1 Lot have commenced and are progressing to final design levels. A review of the controls in relation to the proposed staging of works on the site was undertaken to ensure effective control implementation and to offer potential modifications to the existing ESC measures for 					
		 works under the occupation of Burtons Contractors. The inspection reviewed the establishment on the site and the implementation of initial erosion and sediment controls and basins associated with the WH1, WH3 and WH2 Lots. The earthworks for WH1 Lot have commenced and are progressing to final design levels. A review of the controls in relation to the proposed staging of works on the site was undertaken to ensure effective control implementation and to offer potential modifications to the existing ESC measures for improved management and effective construction practices. Dust and water management on site are performing well with no visible dust observed and drainage swales installed with check controls for water 					
		 works under the occupation of Burtons Contractors. The inspection reviewed the establishment on the site and the implementation of initial erosion and sediment controls and basins associated with the WH1, WH3 and WH2 Lots. The earthworks for WH1 Lot have commenced and are progressing to final design levels. A review of the controls in relation to the proposed staging of works on the site was undertaken to ensure effective control implementation and to offer potential modifications to the existing ESC measures for improved management and effective construction practices. Dust and water management on site are performing well with no visible dust observed and drainage swales installed with check controls for water transfer were operating effectively following recent rainfall. 					
		 works under the occupation of Burtons Contractors. The inspection reviewed the establishment on the site and the implementation of initial erosion and sediment controls and basins associated with the WH1, WH3 and WH2 Lots. The earthworks for WH1 Lot have commenced and are progressing to final design levels. A review of the controls in relation to the proposed staging of works on the site was undertaken to ensure effective control implementation and to offer potential modifications to the existing ESC measures for improved management and effective construction practices. Dust and water management on site are performing well with no visible dust observed and drainage swales installed with check controls for water transfer were operating effectively following recent rainfall. The site is very tidy and organized and is well presented with designated 					
		 works under the occupation of Burtons Contractors. The inspection reviewed the establishment on the site and the implementation of initial erosion and sediment controls and basins associated with the WH1, WH3 and WH2 Lots. The earthworks for WH1 Lot have commenced and are progressing to final design levels. A review of the controls in relation to the proposed staging of works on the site was undertaken to ensure effective control implementation and to offer potential modifications to the existing ESC measures for improved management and effective construction practices. Dust and water management on site are performing well with no visible dust observed and drainage swales installed with check controls for water transfer were operating effectively following recent rainfall. The site is very tidy and organized and is well presented with designated access routes and signage. Controls are maintained and appear effective. 					
		 works under the occupation of Burtons Contractors. The inspection reviewed the establishment on the site and the implementation of initial erosion and sediment controls and basins associated with the WH1, WH3 and WH2 Lots. The earthworks for WH1 Lot have commenced and are progressing to final design levels. A review of the controls in relation to the proposed staging of works on the site was undertaken to ensure effective control implementation and to offer potential modifications to the existing ESC measures for improved management and effective construction practices. Dust and water management on site are performing well with no visible dust observed and drainage swales installed with check controls for water transfer were operating effectively following recent rainfall. The site is very tidy and organized and is well presented with designated access routes and signage. Controls are maintained and appear effective. The installed controls are working well for effective sedimentation 					
		 works under the occupation of Burtons Contractors. The inspection reviewed the establishment on the site and the implementation of initial erosion and sediment controls and basins associated with the WH1, WH3 and WH2 Lots. The earthworks for WH1 Lot have commenced and are progressing to final design levels. A review of the controls in relation to the proposed staging of works on the site was undertaken to ensure effective control implementation and to offer potential modifications to the existing ESC measures for improved management and effective construction practices. Dust and water management on site are performing well with no visible dust observed and drainage swales installed with check controls for water transfer were operating effectively following recent rainfall. The site is very tidy and organized and is well presented with designated access routes and signage. Controls are maintained and appear effective. The installed controls are working well for effective sedimentation control. 					
		 works under the occupation of Burtons Contractors. The inspection reviewed the establishment on the site and the implementation of initial erosion and sediment controls and basins associated with the WH1, WH3 and WH2 Lots. The earthworks for WH1 Lot have commenced and are progressing to final design levels. A review of the controls in relation to the proposed staging of works on the site was undertaken to ensure effective control implementation and to offer potential modifications to the existing ESC measures for improved management and effective construction practices. Dust and water management on site are performing well with no visible dust observed and drainage swales installed with check controls for water transfer were operating effectively following recent rainfall. The site is very tidy and organized and is well presented with designated access routes and signage. Controls are maintained and appear effective. The installed controls are working well for effective sedimentation 					
4.	Summary of	 works under the occupation of Burtons Contractors. The inspection reviewed the establishment on the site and the implementation of initial erosion and sediment controls and basins associated with the WH1, WH3 and WH2 Lots. The earthworks for WH1 Lot have commenced and are progressing to final design levels. A review of the controls in relation to the proposed staging of works on the site was undertaken to ensure effective control implementation and to offer potential modifications to the existing ESC measures for improved management and effective construction practices. Dust and water management on site are performing well with no visible dust observed and drainage swales installed with check controls for water transfer were operating effectively following recent rainfall. The site is very tidy and organized and is well presented with designated access routes and signage. Controls are maintained and appear effective. The installed controls are working well for effective sedimentation control. The site is forecasting continuation of earthworks for the WH1 Lot and progression of site activity to design. Works for the trunk drain are to 					
4.	Community	 works under the occupation of Burtons Contractors. The inspection reviewed the establishment on the site and the implementation of initial erosion and sediment controls and basins associated with the WH1, WH3 and WH2 Lots. The earthworks for WH1 Lot have commenced and are progressing to final design levels. A review of the controls in relation to the proposed staging of works on the site was undertaken to ensure effective control implementation and to offer potential modifications to the existing ESC measures for improved management and effective construction practices. Dust and water management on site are performing well with no visible dust observed and drainage swales installed with check controls for water transfer were operating effectively following recent rainfall. The site is very tidy and organized and is well presented with designated access routes and signage. Controls are maintained and appear effective. The installed controls are working well for effective sedimentation control. The site is forecasting continuation of earthworks for the WH1 Lot and progression of site activity to design. Works for the trunk drain are to commence for the installation of final water passage through the site. 					
4.		 works under the occupation of Burtons Contractors. The inspection reviewed the establishment on the site and the implementation of initial erosion and sediment controls and basins associated with the WH1, WH3 and WH2 Lots. The earthworks for WH1 Lot have commenced and are progressing to final design levels. A review of the controls in relation to the proposed staging of works on the site was undertaken to ensure effective control implementation and to offer potential modifications to the existing ESC measures for improved management and effective construction practices. Dust and water management on site are performing well with no visible dust observed and drainage swales installed with check controls for water transfer were operating effectively following recent rainfall. The site is very tidy and organized and is well presented with designated access routes and signage. Controls are maintained and appear effective. The installed controls are working well for effective sedimentation control. The site is forecasting continuation of earthworks for the WH1 Lot and progression of site activity to design. Works for the trunk drain are to commence for the installation of final water passage through the site. 					

	Summary of Complaints	There were no complaints received during the reporting period.					
		Date Details					
		NIL					
	Summary of Incidents	There were no incidents	notified to the Departme	ent during the repo	orting period.		
		Date Details					
		NIL					
	Summary of non- compliances	During the reporting period, a non- compliance with condition B26 was noted by the ER as erosion and sediment controls implemented for the Warehouse # 3 catchment were inconsistent with the approved Erosion and Sediment Control Plan (P92_YBA_GPT_23-00001-ESC-RB (REV 1.5))					
	Evaluation of	The ER's evaluation of E	nvironmental Performanc	e is based on:			
	Environmental Performance		nitoring data for dust, noi	se and traffic			
		 Review of com Monthly CPESO 	plaints and incidents				
		Stakeholder fe					
		ER site inspect	ions.				
		Further discussion of environmental performance is presented below.					
		TRAFFIC					
			EMP (section 5.1 - Environe The ER and DPHI if those v		ng and Inspections), the principal exceeded:		
		Light Vehicle:Heavy Vehicle:	570 movements 550 movements				
		AM Peak: (07:00 – 08:0	0)				
		PM Peak: (14:00 – 15:0					
		(15:00 – 16:0					
		- AM Peak:	s described in the CTMP		s, in & out combined)		
		- PM Peak:			s, in & out combined)		
		- Daily:			nts, in & out combined)		
		Note: 1 truck is equal to movements.	1 inbound movement plu	us 1 outbound mo	vement which equals to a total of 2		
				ting period and no	otes that there were no exceedanc		
		DUST					
		associated with increasin concentration provides of concentration can be ma	ng risk of off-site particula opportunity for measures anaged effectively.	ate impacts. Note to be implemente	opriate management response / a that an exceedance of the 1-hour I ed to ensure that the 24-hour aver sented in the table below.		
		Pollutant	Averaging Period	Units	Criteria		
		Particulates (as PM ₁₀)	24 hours	μg/m ³	50		
			Annual	μg/m ³	25		
		Particulates (as PM _{2.5})	24 hours	μg/m ³	25		
	l l		Annual	µg/m³	8		

		Date and Tin	ne	Exceedance	Location	Comments		
		19/09/2024 at 11:00 pm		57 μg/m³	Mamre Rd (center)	Exceedance occurred during the night. No works during this time		
		24/09/2024 a	•	51.6 μg/m³	Mamre Rd (center)	night. No works during this time		
		29/09/2024 at 03:00 pm		54.3 μg/m ³	Mamre Rd (center)	Exceedance occurred on Sunday. No works during this time.		
		Recommendations - Dust						
			-		f the site and utilisation of dust suppression (watering) leted areas to minimises dust generation			
9.	Analysis of Lesson Learnt and Opportunities for improvement	• Where practical to do so, accelerating the installation of final landscaping and paved surfaces to prevent dust generation and minimise erosion risk.						
10.	Any changes to the project including changes	During the previous reporting period, the Erosion and Sediment Control Plan has been revised was subsequently endorsed by the ER. The revised erosion and sediment control plan is with DPHI for approva						
	to CEMP and	Documentation				Version and Date (Author)		
	other Project Documentation	ESCP_P92_YBA_GPT_23-00001-ESC-Revision 2.0 Issue 5, 15/04/2024 (OCHRE)						
11.	Any meetings attended by ER	The ER has been involved in the following meetings.						
		Date						
		25/09/2024	Both ERs	a Road Dracinct M	lorking Group mostin			
					orking Group meetir vy representatives of	-		
				es are available up				
12.	Summary of documents issued by the ER	The following	documents w	vere issued by the	ER.			
		Documentat	ion		Version and Date	(Author)		
		ER Letter – Establishment of ERSED controls for Warehouse # 1 undertaken B26 of SSD 10272349			22024-GPT-LTR-240908, 08/09/2024 (R.Peterson)			
		ER Letter – Establishment of ERSED controls for Warehouse # 3 undertaken B26 of SSD 10272349			22024-GPT-B26 -20_9_24, 20/09/2024 (R.Peterson)			
		ER Site inspection Report 24/09/2024 INSP-RPT-COMP-GPT260924, 24/09/2024 (R.Peterson)						
13.	Closing Remarks	At this stage of the project, the management of key environmental risks such as dust, traffic and erosion are satisfactory. During the month, inspections were undertaken by the alternate ER as the primary ER wa ill due to Covid.						

14.									
	Photo	Location and comment	Resolution/Action						
		<u>Site Perimeter – 20/09/2024</u>	OBSERVATION						
		 Environmental monitoring stations have been installed with real- time monitoring for air quality and noise. It was noted during the 							
		inspection that one of the monitors is adjacent to Mamre road and may be influenced by background road noise. This aspect needs to							
	The second second	be considered through monthly reporting.							
		Warehouse # 1 Earthworks – 20/09/2024	OBSERVATION						
		 Several water carts were observed during the site inspection with no dust being generated during the earthworks. 							
	A CLAR	Mulch Stockpile area – 20/09/2024 - Mulch from stockpiling activities was stored in a grassed area and	OBSERVATION						
		outside the dripline of trees. A silt curtain was installed on the low site of the stockpile.							
	an of the procession								
		Warehouse # 3 internal haul road – 20/09/2024	OBSERVATION – ONGOING						
	and the second sec	 Internal haul road has been cut across the dirty water drain RISK – LOW 							
		- Ongoing monitoring and maintenance are required to ensure the							
	A CARANA C	effectiveness of the dirty water drain.							
		Warehouse # 3 ERSED Controls – 20/09/2024							
		 An inspection of the warehouse # 3 erosion and sediment controls 	OBSERVATION						
		was undertaken in accordance with condition B 46. Refer to separate letter and report for details (reference 22024-GPT-B26 -							
		20_9_24)							
	1 / A A								

	 Warehouse # 3 perimeter bund – 20/09/2024 An area of geofabric had become detached from the perimeter bund and requires re-securing. RISK – LOW Re-pin the geofabric to the perimeter bund. 	OBSERVATION Closed on 28/09/2024, Geofabric Pinned and Secured by the construction contractor. Image: Construction of the const
	 <u>Site exit point / access road – 20/09/2024</u> Internal access road is a properly constructed and sealed bitumen road with a rumble grid installed to minimise the risk of mud tracking. 	OBSERVATION
<image/>	 Site Compound – 20/09/2024 Signage has been installed at the site entry and exit point instructing personnel of the requirements of the CTMP with a warning of the consequences (\$15,000) fine if they fail to meet their obligations. 	OBSERVATION

Attachment 1 – Extract of Consultation and Communication Register

Date	Responsible Rep	In/Out/ Meeting	Initial Communication Method/Tool	Contact Name/ Organisation	Nature of Complaint/Enquiry/ Communication	Summary of Issues/Details of Communication	Resolution
NIL							